


## HRV Spare Parts

## Customer- General

\*Changed from XP40461 to XP40461A Jan 2013, for units manufactured around this date check serial No's with Technical to determine which motor is required.

If XP40461 is required use XP4056


# Control PCB XP41262 firmware was upgraded to FW0046 from FW0020 January 2019, PCB's are interchangeable



XP40062 Control PCB



XP40462 'ABS' Control PCB



XP40262 'A' & 'ABD' Control PCB



XP40862 'MB' Control PCB



XP41262 'HMB' Control PCB



XP40362 ABS & ABD Power PCB



XP40762 'MB' & 'HMB' Power PCB



XP41062 B units - Control & Power PCB

Firmware Version Numbers may Vary, Please check with Titon Technical for Advise.